
AUTO LABEL APPLICATING MACHINE

MODEL NO: SL-LX350XL-V2B




1. INSTALLATION

- 1.1 The preparation for machine installation
 - 1.The auto label applicating machine model No. LX-350N is 1500 kg weight. There are 4 casters under the machine. It can be moved easily.
 - 2.It is required at least 3 persons for machine moving.
 - 3. The workers should wear protecting clothing such as safety helmet, protecting shoes and gloves etc.
 - 4. The machine can be only moved on the smooth place. It is possible to fall down if move on the rough or massy surface.
 - 5.If it needs to use lifter, it will be required for 1.25 tons capacity. Also a licenced operator is requested.




1.2 The position of installation

- 1. Whe the machine set on required location, please take off the covering plastic film.
- 2. To adjust correctly for the applicating position and must line-up the former on the center line of conveyor.





- 3. Using the wrench to adjust the screw at the legs to level the machine reach to demanding height.
- 4. If it is necessary, the expanding screws may be adopted to fix the machine.



6. Completing the installation.

Top view





1.3 The requirement of electricity & air compression


- 1. The power supply is required for 3 phase 480V 50/60 HZ.
- 2. The air compression is necessary. The 5.5kg/square cm (80 psi) pressure is required if any attached accessories demanding the air compression.
- 3. The ground wire must be wired.

2. THE COMPONENTS OF MACHINE

2.1 GENERAL INSTRUCTIONS

1. Preface

Thank you to purchase our product. By this manual, we would like to provide you the standard operating procedures and the maintenance.



3. Specification & Capacity

POWER: AC 3 phase 220V, 50/60HZ

MOTOR: 25W X2, 40W X1,400W X2, 2000W X2, 750W X1

LAY FLAT WIDTH: 70-220 m/m

LENGTH: 45-200 m/m

THICKNESS: 0.035-0.07 m/m

APPLIED MATERIAL: OPS, PVC, PET

SPEED: MAX.500 BOTTLE/MIN.

^{**} Speed will be varied with shape of bottles, types, thickness and length of shainkable films, the accurate speed has to be measured in actual situation.

^{**} Reference formula: (object's circumference) / 2 + (3-5m/m).

2.2 THE NOTICES FOR MACHINE TURNING ON/OFF

- All the operators who should study this manual thoroughly before operating the machine.
 If those operators do not follow the rules to run the machine
 - leading to injury, NAFM won't be responsible for the wounded.
- 2. Please check following items before turning on the machine.
 - 2.1 To check the attaching accessories on the machine.
 - 2.2 To make sure the conveyor table is clean.
 - 2.3 To roll the feeding & applicating rollers by hand, making sure all parts run smooth.
 - 2.4 To check the plastic tube, which has no jam.
 - 2.5 Do not place the tools on the machine to avoid the danger of rolling in.
 - 2.6 To check the emergency button on standing by position in anytime.
- 3. To ensure safety, do not open the machine cover when the machine is running.
- 4. There is a safety device which is set on machine. When the machine is running, it will stop immediately and start alarm if open the door.
- 5. The machine must be stopped running for adjustment and maintenance.
- 6. The operator should pay attention for the caution marks and follow the rules for safe operating.
- 7. The machine should be operated or maintained by the experienced operator or technician.
- 8. It would be dangerous to operate the machine by a tyro.
- 9.To prevent from danger, in any case, never pull out & turn off the safety switch when the machine is electrified. Also, keep off your hands & any tools in the scope of cutting zone.
- 10.All operators must strictly observe the above guild line and keep the machine clean & well-run.

WARNING SIGNS



Caution sign, be alert.



Grounded sign, Notice here is the grounded location. Please ground the earth cable to Class-3(lower than 100 $\,\Omega$). Incomplete grounding connection may lead to electric shock.



Electrical hazard, electrical danger if touched.

Only the trained electrician can uncover the electric panel or box.



Cut warning.

In any case, do not place your hands or any object on the sealing or cutting zone. Shut down the machine before doing the maintenance, parts replacing or trouble shooting in the these zones.



Pinch warning.

Do not put your hands or any object on the moving mechanism. Shut down the machine before doing the maintenance, repair or adjustment.



Crush hazard.

Do not put your hands or any object on the moving mechanism. Shut down the machine before doing the maintenance, repair or adjustment.




High temperature warning.

Do not touch or close to the heating source to prevent from getting burn. Proceed any maintenance only when the temperature of heater or heating source cool down to room temperature.




Moisture warning, keep dry.

3. Film fitting




Film supply device (option)



Option device

Film accumulator model: AUS-300




4. The touch panel


Machine startup - first page (B6)




After machine startup, it will display this page .

Press "FAULT RESET" button, cutter will positioning







- 1. Without using the print reading sensor
 - a.Press "SETTING" to go to the setting screen
 - b.PRINT set "NO".
 - c.Setting the cut length.

Press "SET",the keypad will appear. Input the digits.

EX. 100.0 ENT

- d.Press "MANUAL" to go to the manual screen
- e.Press "CYCLE" ,test run the machine to check is it working according with the set up was planned or not?

 (Must test run at lease 3 time to check the label is it being cut ok?)
- f.Press "START" button.
- g.Test run with the actual object being packed, adjust the work detective sensor's position to aim the label to insert to the objects perfectly.


2. With using the print reading sensor

- a.Press "SETTING" to go to the setting screen
- b.PRINT set "YES"
- c.Setting the cut length.

Measurement the frame length by ruler, then keyin the data. Press "SET", the keypad will appear.

- d.Set the PRINT REG. DWELL TO "0".
- e.Press "MANUAL" to go to the manual screen.
- f.Press "CYCLE" ,test run the machine to check is it working according with the set up was planned or not?

 (Must test run at lease 3 time to check the label is it being cut ok?)



- g.Press "SETTING" to go to the setting screen h.Modify the PRINT REG. DWELL setting.

 PRINT REG. DWELL = 30.5 mm
- i.Press "START" button.
- j.Test run with the actual object being packed,adjust the work detective sensor's position to aim the label to insert to the objects perfectly.

DRAWING: B133 (PRODUCT SELECTION SCREEN)



Only press on to this sign for 3 seconds.


You can change lock/unlock positions. Details can not be corrected at the locked position.

1.Press P1 key for the first to fifth group.

Press P2 key for the sixth to tenth group.


As shown abore, we can store 40 group.

- 2.Press SELECT key, you can more these material to the working area.
- 3.Press RENAME key will automatically show key pad. You can then make changes to names for the group.
- 4. Press EXIT key , verity the choices and return to the B3 setup page.




- 1.Press the SET key ,you can setup the hight of the machine head.
- 2.Press the MANUAL key.Then press the key,you can adjust the machine head with no restrictions.
- 3.Press SEMI-AUTO POSITION key.Then press the key.

 The machine head automatically adjusts the machine head and stops.





- NO.4: Only make records and display functions.
- NO.5 : Can choose speed with applicating wheel.
- NO.6 :Can adjust speed of timing screw motor.
- NO.7: Only make records and display functions.

DRAWING: B51




NO.7: Only make records and display functions.






DRAWING: B218 (ALARM & MESSAGE)




If "Low film" appears on display,please press clear key. The message will then be removed.


5.1 Change the cutter


5.1.1 Remove 4 screws






5.1.2 Unbar the loop







5.1.3 Loose the handle by rotating the handle counter to clockwise direction, just loose it, don't have to remove the handle.




5.1.4 Pull out the aluminum cube.




5.1.5 Take off the belt.




5.1.6 Pull out the cutter plate




5.1.7 Loose the screws, and remove the old cutter, replace the new cutter and rotate the screws tightly.




5.1.8 After the cutter amending, plug in the cutter plate.




5.1.9 Put the belt into the timing pulley




5.1.9 Pull in the aluminum cube and rotate the handle tightly to counter clockwise direction.





5.1.10 To bar the loop





5.1.11 Turn the 4 screws tightlyComplete the cutter amending.























e Check			Revision: 2012-01										SETTING:3			(<u>(</u>			"hsi										Draw	ALAN
Modifier Date	1	1	Rev										TO MODIFY ,FACTORY SETTING :3			((((((SAVE 10 EEPROM)			L SHOW "Fin										Check	
ром				70	Q.	_	pdS-c	DE"	A-00	VICE	TIMES	A-42 "		_	۸-42				<u>-</u>	PRESS⊕AND HOLD IT,TILL SHOW "Finish"	(' ח	0 0	o	0.	~ "	7200	500	က	Approved	
Description				Setting Method	DISPLAY: r0	PRESS "SET"	DISPLAY: dp-Spd	PRESS " MODE"	DISPLAY: PA-00	PRESS TWICE	PRESS (*) PRESS (*) 4 TIMES	DISPLAY: PA-42	PRESS SEI PRESS ⊕⊕	PRESS "SET"	DISPLAY: PA-42	PRESS "MODE"	DISPLAY: EE-SEI	PRESS "SET"	DISPLAT . E	PRESS⊕AN	i i i	A5 SETTING	Pr-0.00:0	Pr-0.02: 1	Pr-0.03: 20	Pr-0.02: 0 Pr-0.07 : 3	P-0.07	Pr-0.11 500	Pr-5.17 :	Date	06.01.2012
Mark		[2] -				20	P.G.		-a	25 GND	24																			Machine codename	LX350N
						40 42 44 46 48		39 41 43 45 47 49	٦	15 17 19 21 23 GND GND CZ OA+ OZ+	20 22	Q -		Wire NO#	+240	3.13 +2///	7+ 7 -	PLS3	1240	DIR3	Λ0	Λ0	1.01	٧5		OA-	OA+	0B+	-80 0	Electric circuit diagram	LX350N-J007
						38	<u>ප_</u>	37	ALM+	11 BRK- GND	12	7	:	Function	+ CO L	VERON PI 0.1		PULSZ PICNI	0.00	SIGNZ	COM-	ALARM-	ALARM+	占 :	shield	OA-	OA+	0B+	OB- shield		No
			ICA1 2KW A5II	or:SCSI2-50P		32 34	. C- S- MODE RDY-	31 33 A	CLR INH RDY+	3 5 7 9 PULS1 SIGN1 COM+ CCWL	4 6 8 10	Z SIGNZ CWL BRK-	:	50Pin NO#	\ C	, Kg) -	4 u	o ,	9	41	36	37	30	13	21	22	48	49 25	Drawing name	Drawing 1
		Feed Servo Motor Driver	ModeMEDKT7364CA1 2KW A5II	50PINS Connector:SCSI2-50P		26 28 30		27 29	NO- O- NO-	/ 1 3 5 NC PULST SI	2 4			Wire Color	Gray	Green	و وق	Keu Gray	. Ciay	White	Blue	Yellow	Black	Orange		Red	Black	Green	White		





Chest.	CIECK		Revision: 2012-01								E: 9NIL															Draw	ALAN	
change note	+	ı	Revisio								 TO MODIFY ,FACTORY SETTING :3		(SAVE TO EEPROM)		L SHOW "Finish'											Check		-
Design				po	5	T	ap-spa	JUE" PA-00	TWICE	4 TIMES PA-42	T" Y⊕ TO MODIFY	"_ <		T" EEP-	PRESS⊕AND HOLD IT,TILL SHOW "Finish"			<u>(</u>	<u>9</u>	0 0	2: 1	0 0	Pr-0.07:3	2:7200		Approved		
C. Haire	nescription			Setting Method	DISPLAY:	PRESS "SET"	DISPLAY: ap-spa	PRESS " MODE" DISPLAY : PA-00	PRESS (1)	PRESS (**) PRESS (**) 4 TIME	PRESS "SET" PRESS	PRESS "SET"	DISPLAY: PA-42 PRESS "MODE" DISPLAY: EE-SET	PRESS "SET" DISPLAY: EEP-	PRESS⊕A			 	A5 SELTING Pr-0 00 : 0	Pr-0.01:0	Pr-0.02: 1	Pr-0.02: 0	Pr-0.07:3	.0-1-2 20.0-1-2		Date	06.01.2012	
Most		<u>2</u> –						FG	-8C	25 GND	24 0Z-															Machine codename	LX350N	
							42	뒽	37 39 41 43 45 47 49 ALM+ COIN+ COM- SP PULSH2 SIGNH2 OB-	15 17 19 21 23 GND CZ OA+ 0Z+	14 16 18 20 22 2 SPR CCWTI CWTL NC OA- 0				Wire NO#	+24V	3.15	+24V	PLS4	+24V	DIR4	//0	/0	1.03		Electric circuit diagram	LX350N-J009	
							36 38	ALI		13 	╛			:	Function	COM+	SERON	PULS1	PULS2	SIGN1	SIGN2	COM-	ALARM-	ALARM+ shield))		No	
			2 2 2 2 2	AT ZKW ASII		tor:SCSI2-50P	32	SE SE	29 31 33 35 SRV A- INH S-	_	4 6 8 10 PULS2 SIGN2 CWL BF				#ON UNG	7	29	က	4	5	9	41	36	37	!	Drawing name	Drawing	-
		Cutter Servo Motor Driver		Model: MEDK1/364CA1 ZKW ASII		50PINS Connector:SCSI2-50P		VS-SEL DIV	27 29 GAIN SRV	1 3 -0N NC PULS1 5	NC PULS				Wire Color	Orange	Green	Purple	Red	Gray	White	Blue	Yellow	Black				





	Description Modifier Date Check	1	1	Revision: 2012-01		Jethod	ნ : ≻	"SET"	DISPLAY: dp-Spd	PRESS "MODE"	DISPLAY: PA-00 PRESS (**) TWICE	•	PRESS 4 TIMES DISPLAY: PA-42	"SET"	PRESS ** TO MODIFY FACTORY SETTING :3 PRESS "SET"	DISPLAY: PA-42 PRESS "MODE" DISPLAY: EE-SET (SAVE TO EEPROM)	PRESS "SET" DISPLAY: EEP-	PRESS⊕AND HOLD IT,TILL SHOW "Finish"				A5 SETTING	Pr-0:00 : 1 (0:CW ; 1:CCW) Pr-0:01 : 0	Pr-0.07 : 3	Pr-0.08: 1000 (1000 P/R)		moved Check	in the second distribution of the second distrib
_	Mark Desci	<u>-</u>	<u>2</u> –			Setting Method	DISPLAY: r0	PRESS "SET"	DISPLA	PRESS	DISPLA	PRESS (PRESS DISPLA	PRESS "SET"	PRESS ®®	DISPLA PRESS DISPLA	PRESS "SET" DISPLAY : EE	PRESS				A5 S	<u>.</u> .	- 0	. С		Machine codename Date	+
										46 48 50	SIGNH1 OB+	45 47 49 PULSH2 SIGNH2 OB-	21 23 25 04+ 07+ 6ND		OA- OZ-		#				_						Aisam Machine	idgi aiii
										44	<u>~</u>	37 39 41 43 45 ALM+ COIN+ COM- SP PUL	13 15 17 19	114 16 18 20	SPR CCWTL CWTL NC TROR /TROR		Function Wire NO#	COM+ +24V		PULS1 +24V	PULS2 PLS1	SIGN1 +24v	SIGN2 DIR1	COM- 0V	ALARM- 0V	ALARM+ 1.05 shield	Tlooten ointent	חוככת וכ כוו כמוד
					.	:510E			or:SCSI2-50P	32 34 36	C- S- ALN MODE RDY-	31 33 35 A- INH S-	CLK	110 112	PULSZ SIGNZ CWL BRK- ZSP		50Pin NO#	2 C	•	3	4 PI	5 S	S 9	41 C	36 AL	37 AL 13 sl	omen suineal	DIG IIII
				Applicating Wheel	DR3 Servo Motor Driver	Model: MBDHT2510E			50Pins Connector:SCSI2-50P	/		SAIN SRV	-0N -0N -0N -0N -0N	-	NC PULS:		Wire Color	Orange	Green	Purple	Red	Gray	White	Blue	Yellow	Black		
































































									_
*	10	5CD36MHMD042G1S	Servo motor	MHMD042G1S 2					
	02	5BC02TRT40M6X20	Turn the handle	TRT40 M6X20 2					
	03 5		Bearings	698ZZ 4					
	20	5BE010696ZZ	Bearings	696ZZ 2	E	_	LX350XL-FC03		
	05 5	5BE016805ZZJ	Bearings	6805ZZJ EZO 6	F30	5BF05LA150FC02 Shaft pulley	LX350XL-FC02	,-FC02 2	6)
	98	5BE016801ZZJ	Bearings	6801ZZJ EZO 4	F29	SHFQLA150FC01 Application	LX350XL-FC01	,-FC01 2	6)
	07	5BB024X122XL	Timing belt	W=1/2" XL L=122 2	F28		LX350-FP05	205 2	6)
	1				F27		LX350-FP04	904	
	<u>L</u>	<u></u>	(F26		LX350-FP03	903	
		-/*		\wedge	F25		LX350-FM43	M43 2	6)
_				₹ √2 /	F24		LX350-FM42	M42 2	6)
	, (0)	/ *X	/ E	01110	F23		LX350-FM41	M41 1	
	.	· · ·			F22		LX350-FM40	M40 1	
(F31) (F31)	*	· \ \			F21		LX350-FM39	M39 1	
90		,' 		F21	F20		LX350-FM38	M38 2	6)
		/\$ /	, / '	"	F19		LX350-FM37	M37 1	
				——————————————————————————————————————	F18		LX350-FM36	M36 1	
(5)					F17		LX350-FM35	M35 1	
(FOI)		/			F16		LX350-FM34	M34 2	6)
(05) (FIOS)					F15		LX350-FM33	M33 2	67
(F30)					F14		LX350-FM32	M32 2	6)
				× ×	F13		LX350-FM31	M31 2	6)
					F12		LX350-FM30	M30 2	6)
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	(((FII		LX350-FM29	M29 2	6)
				(6)	F10		LX350-FM28	M28 2	6)
	$\times /$		·		F09		LX350-FM27	M27 2	6)
		() M	C		F08		LX350-FM26	M26 2	6
	•	Z	(ک		F07		LX350-FM25	M25 2	61
(F16) (F19) (F77)	\\ _			<u></u>	F06		LX350-FM24	M24 2	6)
`	F23)	(F22)	X		F05		LX350-FM23	M23 2	6)
(F17))	(F29)	$\overset{\circ}{\smile}$	· ·	F04		LX350-FM20	M20 1	
(F20)))	F03		LX350-FM19	M19 1	
			B	Belt into the belt	F02		LX350-FM18	M18 1	
(F14)					F01	•	LX350-FM17	M17 1	
					ITEM	PARTS NO. NAME	SPECIFICATION	ATION QTY	7
				Drawing name LX350XL-F02	LX350X	Units Scale	Check	Design Draw	
				Drawing No	LX350XI		6.26	CLAYTON	_
									٦






















	L								
		107					LX350-IP04		
		901				LX	LX350-IP03		
		105				LX	LX350-IM42		4
		104				TX	LX350-IM41		1
		103				LX	LX350-IM40		7
		102				LX	LX350-IM39		2
		101				LX	LX350-IM38		1
	I	ITEM	PARTS NO.		NAME	SPE	SPECIFICATION QTY	O NC	ΊΤΥ
Drawing name LX350XL-106	-TX350XL-	901	Units	Scale	Date	Check	Design	Draw	W
Drawing No	TX350XL-106	901	MM		2014.06.26			CLAYTON	NO
									1

